

Workshop Student Supply List

CraftSummer
Growing artists for over 30 years... 2014

Advanced Bronze Casting

Jim Killy

Week 3 • June 23-27

Studio Location: Hiestand 23/25

Please bring the following supplies to your workshop:

RETURNING STUDENTS- Please pay special attention to this information as numerous changes have occurred and pertain to all participants.

Come to the workshop with a finished wax not to exceed 12" in maximum dimension. If you need microcrystalline sculpture wax contact Jim Killy, 513/523-8096, no later than **June 3**. You **MUST** contact Jim Killy to review your idea prior to the workshop.

Plan on pouring 2 small bronze castings. If you would like to execute something outside those parameters, you **MUST** contact the instructor for approval as supplies, materials and bronze are ordered to accommodate the stated guidelines.

The schedule below shows what to expect from the standpoint of timing and production.

Monday

8:30 Meet, introductions
10 am Slides, gate wax (1)
1 pm Invest wax (1)
2 pm Load kiln (1)
3 pm Begin burnout (1)

Tuesday

8 am From 500 degrees F to 1175
8 am Begin new wax (2)
2 pm Invest (2)

Wednesday

5 am Open kiln (instructor)
8:30 Pack investments
9 am Charge furnace (1)
10 am Pour Bronze (1)
1 pm Load kiln (2)
2 pm Begin burnout, 500 degrees F. (2) Divest and clean bronze (1)

Thursday

7 am Clean bronze (1)
1 pm Patina bronze (1)

Friday

5 am Open kiln (instructor)
9 am Charge furnace (2)
11 am Pack investments (2)
noon Pour bronze (2)
1 pm Divest and clean bronze (2)
3 pm Clean up workshop, studio tour

Bring gloves, metal files-small medium-fine, small cold chisel, small hammer, safety glasses

Optional: Dremel tool with metal working bits.

(updated 2/25/14)

Supply Fee All workshops have a minimum \$10 studio fee. Fees are collected at the end of the workshop and are payable by check or credit card. **MU no longer accepts cash.** The estimated fee for this workshop is:

You also can expect to pay a supply fee of \$75-100 for materials provided in the workshop plus \$6/LB for bronze (cost of bronze fluctuates with the current market price) and general \$10 studio fee.

Workshop locations shown on supply sheets are subject to change. If you have any questions, please contact Billie Sirm, Workshop Coordinator, in the CraftSummer office at 513/529-7395, or by e-mail at CraftSummer@miamioh.edu.

Workshop Student Supply List

*Craft*Summer
Growing artists for over 30 years... 2014
